

Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
EDGEDALE ROAD	O/S 102	Damaging	Damage to Surface	Aesculus hippocastanum	Plant in new 800mm pit o/s-between 100- 98 (relocated 5 m due to driveways access)	Corylus colurna
EDGEDALE ROAD	o/s 86	Damaging	Damage to Surface	Acer pseudoplatanus	Plant in new 800mm pit o/s 86 (same as felled tree)	Liquidambar styraciflua 'Worpl
EDGEDALE ROAD	o/s 78	Damaging	Damage to Surface	Acer pseudoplatanus	Plant in new 800mm pit o/s 78 (same as felled tree)	Corylus colurna
EDGEDALE ROAD	o/s 70	Damaging	Damage to Surface	Acer pseudoplatanus	Plant in new 800mm pit o/s 70 (same as felled tree)	Liquidambar styraciflua 'Worpl
EDGEDALE ROAD	o/s 32	Damaging	Damage to Surface	Acer pseudoplatanus	Plant in new 800mm pit o/s 32 (same as felled tree)	Corylus colurna
EDGEDALE ROAD	o/s 6	Damaging	Damage to Surface	Acer pseudoplatanus	Plant in new 800mm pit o/s 6-8 (same as felled tree)	Liquidambar styraciflua 'Worpl
EDGEDALE ROAD	o/s church (2nd tree on road from bottom)	Damaging	Damage to Surface	Acer pseudoplatanus	Plant in new 800mm pit o/s church (same as felled tree)	Corylus colurna
EDGEDALE ROAD	o/s 3-11 Javelin House (facing junction with Edgemount Rd)	Damaging	Damage to Surface	Acer pseudoplatanus	Plant in new 800mm pit opp junction with Edgemount Rd (same as felled tree)	Liquidambar styraciflua 'Worpl